INSTALLATION RESTORATION PROGRAM

Final DECISION DOCUMENT UST SITE 380


117th Refueling Wing Alabama Air National Guard Birmingham Airport Birmingham, Alabama

January 1997



DTIC QUALITY INSPECTED &

19970915 072



REPORT DOCUMENTATION PAGE

Form Approved OMB No. 074-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of the collection of information, including suggestions for reducing this burden to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE Jan 97	3. REPORT TYPE	AND DATE COVERED	
4. TITLE AND SUBTITLE DECISION DOCUMENT, UST 380, 117 TH REFUELING WING, Alabama Air National Guard, Birmingham Airport, Birmingham, Alabama		5. FUNDING NUMBERS		
6. AUTHOR(S) CH2M Hill, Inc.				
7. PERFORMING ORGANIZATION NAME(S)	AND ADDRESS(ES)		8. PERFORMING ORGA	NIZATION REPORT NUMBER
CH2M Hill, Inc. Hazardous Waste Remedial Actions Program, Martin Marietta Energy Systems, Inc. Oak Ridge, TN 37840				
9. SPONSORING/MONITORING AGENCY NA	ME(S) AND ADDRESS(ES)		10. SPONSORING/MON	ITORING AGENCY REPORT NUMBER
ANG/CEVR 3500 Fetchet Ave Andrews AFB MD 20762- 5157				
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION/AVAILABILITY STATEM unlimited distribution	ENT			12b. DISTRIBUTION CODE
13. ABSTRACT (Maximum 200 Words)				
The Installation Restoration Program was initiated by the Air National Guard (ANG) to evaluate potential contamination to the environment caused by past practices at its installations. During the 1987 Preliminary Assessment (PA), ten abandoned underground storage tanks (USTs) were identified at nine sites. UST 380 was removed from the area west of Building 301 in January 1991. No soil staining or fuel odors were observed during trenching around the tank and the tank was in good condition (no holes or corrosion). The Alabama Department of Environmental Management issued a letter in May 1991 stating it would not require further action at this site. The report thus recommends no further action need be taken at this UST site.				
44 OUD IEST TERMS			15. NUMBER OF PAGE	3
14. SUBJECT TERMS Installation Restoration Program, Air National Guard,			15 pages	•
USTs, Birmingham International Airport, Alabama, ADEM			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CL OF ABSTRAC		20. LIMITATION OF ABSTRACT

General

General

General

none

INSTALLATION RESTORATION PROGRAM

DECISION DOCUMENT SITE UST 380

117 AIR REFUELING WING ALABAMA AIR NATIONAL GUARD BIRMINGHAM AIRPORT BIRMINGHAM, ALABAMA

Submitted to:

AIR NATIONAL GUARD READINESS CENTER ANDREWS AIR FORCE BASE, MARYLAND

Modified and Submitted by:

HAZARDOUS WASTE REMEDIAL ACTIONS PROGRAM MARTIN MARIETTA ENERGY SYSTEMS, INC.
OAK RIDGE, TENNESSEE

for the
U.S. DEPARTMENT OF ENERGY
UNDER CONTRACT NO. DE-AC05-840R21400

Prepared by:

CH2M HILL, INC. MONTGOMERY, ALABAMA

JANUARY 1997

Copies of this report may be purchased from the:

National Technical Information Service 5285 Port Royal Road Springfield, Virginia 22161

Federal Government agencies and contractors registered with the Defense Technical Information Center should direct requests for copies of this report to:

Defense Technical Information Center 8725 John J. Kingman Road, Ste 0944 Ft. Belvoir, VA 22060-6218

CONTENTS

Acron	yms	ii 1
1.	Introduction	2
2.	Background	2
	2.1 Program Background	
	2.2 Site Description	
	2.3 Environmental Setting	
	2.4 Tank Removal Observations	0
3.	Control Measures	9
J.	3.1 Screening	9
	3.2 Identification	9
	3.3 Evaluation	
4.	Conclusions	D
Appen	dix: ADEM Response to Closure Assessment Report	
FIGUI	RES	
1	Alabama Air National Guard Location Map	3
2	UST Location Map	4
3	UST 380 Site Map	7
TABL	E	
2.1	Total Petroleum Hydrocarbons -UST 380 Pit	9

ACRONYMS

ADEM	Alabama Department of Environmental Management
ANG	Air National Guard
ANGRC	Air National Guard Readiness Center
DOD	Department of Defense

DOD Department of Defense DOE Department of Energy

AANG

HAZWRAP Hazardous Waste Remedial Actions Program

Alabama Air National Guard

IRP Installation Restoration Program
NFAR No Further Action Required
NGB National Guard Bureau

PA/SI Preliminary Assessment/Site Investigation

ppb parts per billion ppm parts per million

RD/RA Remedial Design/Remedial Action

RI Remedial Investigation

RI/FS Remedial Investigation/Feasibility Study

SI Site Investigation

TCLP Toxicity Characteristic Leaching Procedure

TPH Total Petroleum Hydrocarbon UST Underground Storage Tank

EXECUTIVE SUMMARY

As part of the Installation Restoration Program (IRP), the Air National Guard Readiness Center (ANGRC), previously known as the National Guard Bureau (NGB), and the Alabama Air National Guard (AANG) requested field observation and sampling during the removal of Underground Storage Tank (UST) 380. The investigation was begun to determine the presence or absence of contamination and the risk to public health and environment, if any, associated with past operations at this site.

This document was prepared to review the available data, to evaluate alternative actions, to make recommendations concerning future action, and to fulfill the requirements and objectives of the National Environmental Policy Act.

UST 380 was removed in January 1991. No soil staining or fuel odor were observed during trenching around the tank for soil sampling. The tank was observed to be in good condition. No holes or corrosion that interfered with tank operation were observed.

The results of laboratory analysis of samples collected from the soil next to the tank indicate that the remaining soil contains detectable levels of total petroleum hydrocarbon (TPH). Potential groundwater receptors are more than 1 mile away from the site.

The Alabama Department of Environmental Management (ADEM) issued a letter in May 1991 stating that it would not require further action at this site. Because ADEM's corrective action limits were met, it is recommended that UST 380 be removed from further IRP consideration and that no further action be required.

1. INTRODUCTION

The objectives of the Decision Document are to present the history of Underground Storage Tank (UST) 380 at Birmingham's Alabama Air National Guard (AANG) facility, to discuss observations made while excavating the tank, to identify and evaluate control measures, and to present conclusions and decisions about the disposition of each UST site. Decisions are based on regulations set forth in the site investigation (SI) work plan dated November 1989.

Figure 1 shows the general location of the AANG facility. Figure 2 shows the specific location of UST 380 on the base. Evaluations are based on criteria set forth in the <u>Site Investigation Work Plan, Alabama Air National Guard</u> (CH2M HILL, Inc., November 1989).

2. BACKGROUND

2.1 PROGRAM BACKGROUND


The Air National Guard Readiness Center (ANGRC), through the Air National Guard (ANG), initiated an Installation Restoration Program (IRP) in response to the policies of the Department of Defense (DOD). The IRP was developed as a phased program for identifying and addressing environmental contamination caused by past practices at ANG installations.

The ANGRC entered into an interagency agreement with the Department of Energy (DOE), under which the DOE will provide technical assistance for implementing the IRP. The Hazardous Waste Remedial Actions Program (HAZWRAP), as a DOE contractor, is responsible for managing this effort under the interagency agreement.


The IRP, along with other national hazardous waste cleanup programs, follows the terminology and procedures of the National Contingency Plan:

- PA/SI Preliminary Assessment/Site Investigation
 RI/FS Remedial Investigation/Feasibility Study
- RD/RA Remedial Design/Remedial Action

This Decision Document is written to provide the basis for the decision not to do any further work. The UST was removed during the SI implemented through the IRP.



ANG LÖĞÄTİĞI Birmingham Air National Guard, Birmingham, Alabamo



2.2 SITE DESCRIPTION

The 117th Tactical Reconnaissance Wing is located next to and north of the Birmingham Municipal Airport, Birmingham, Alabama. This AANG installation has been active at its present location since 1938. Through the years, the base has had several missions, with past and present operations involving the use of USTs for containment of heating fuels, diesel fuels, and jet propulsion fuels.

UST 380 was a 280-gallon fuel storage tank located on a hill adjacent to the ANG communications tower. Tank age could not be determined from base records, but the estimated last use was in 1980. The tank was suspected to have contained diesel fuel and was removed in January 1991. Figure 3 presents the UST 380 site map.

2.3 ENVIRONMENTAL SETTING

2.3.1 Geology

The bedrock beneath the Base consists of the Ketona Dolomite and Knox Group. A mottled-colored cherty clay residuum, resulting from the dissolution of the bedrock, overlies dolomites of these units and averages 30 feet in thickness over the base. Some areas of the Base have visible outcrops of dolomite and chert boulders which are isolated in the clay residuum; chert float can be seen at the surface base-wide.

The residual cherty clays are generally homogeneous, although slight changes in the amount of chert, plasticity and stiffness are present. Dolomitic sand lenses are gravelly clays are present, generally occurring at the contact of clay and bedrock.

2.3.2 Hydrogeology

The uppermost aquifer at the Base is the Knox aquifer. The top of the aquifer is the saturated permeable interface between the residual clay and the bedrock. The clay materials above the bedrock are also generally saturated at shallow depths, 10 to 15 feet below land surface. These clays generally do not yield significant quantities of water.

The direction of groundwater flow in both the clay residuum and the Knox is to the south; a downward vertical component exists in the clay residuum. Data from slug testing of monitoring wells completed in the clay indicate an average hydraulic conductivity of 9.02E-4 ft/day. Because of the low permeabilities exhibited by the residual clays, lateral transport is inhibited.

2.3.3 Water Utilization

Drinking water in the Birmingham is provided by city/county utilities from surface water sources. The municipal water source nearest the Base is the Cahaba River, located approximately 20 miles to the east. Residences adjacent to the Base have been served by the municipal water system for about 60 years.

2.4 TANK REMOVAL OBSERVATIONS


A program to evaluate abandoned USTs at the Birmingham AANG facility included identifying abandoned tank locations, sampling tank contents, preparing tank removal plans and specifications, removing tanks and contaminated soil, and evaluating investigation-derived wastes after the removal effort was complete.

The tank was removed in January 1991. Soil samples were taken from the bottom one-third of the excavation at the UST 380 site, from each of the four side walls, the pit bottom, and the spoil pile generated during the process. Field screening tests (headspace readings) were conducted with a photoionization detector, manufactured by HNu Systems, to indicate contamination and estimate the extent of total petroleum hydrocarbon (TPH) present in the soil. Soil samples were placed in glass jars and covered with foil to create a headspace in the top half of the jar. The HNu probe was inserted through the foil cover into the headspace above the soil approximately 5 minutes after sampling to indicate if TPH was present in the soil sample. The headspace readings with the HNu resulted in a reading of zero parts per million (ppm); therefore, no additional excavation was conducted.

Analytical samples were collected from the same locations as the field screening samples within the pit once all excavation was complete. These laboratory soil samples were analyzed for TPH (EPA Method 418.1), total lead (EPA Method 7421), and ignitability (EPA Method 846[1C]).

UST 380 appeared to be in good condition upon removal; no holes or corrosion were found. No soil staining was observed during the excavation and water was not encountered in the tank pit.





HNu HEADSPACE READING		
LOCATION	(ppm)	
130-N	4	
130-S	28	
130-E	3	
130-W	4	
130-B	44	
130-SP	30	

Note: Readings based on initial calibration of 100 ppm isobutylene = 55.

FIGURE 2.6
UST 130 SITE MAP
Alabama Air National Guard, Birmingham, Alabama

СЕМНІЦ

Field screening tests (headspace readings) for the soils remaining in the excavation did not indicate soil contamination, and the excavation was backfilled. No soil was removed from the excavation for offsite disposal.

Alabama Department of Environmental Management (ADEM) guidance for remediation of soils at UST sites set forth in the SI work plan was 100 ppm TPH for soil samples.

Total lead concentrations of 5 mg/kg also were considered a remedial action criteria. If total lead concentrations are below 5 mg/kg, then no action is required. If the total lead concentrations are higher than the 5 mg/kg limit, then a toxicity characteristic leachate procedure (TCLP) lead analysis is required to determine if the soils need to be managed as a hazardous waste.

ADEM criteria led to the following soil disposition criteria:

- Visually stained soil was removed to the soil staging area for remediation by aeration.
- Soils containing less than 5 mg/kg lead and less than 100 ppm TPH (analytically) were used as general fill material on the AANG grounds.
- Soils containing more than 100 ppm TPH were aerated onsite in aeration beds until TPH levels were below the 100 ppm TPH limit.

Table 2.1 shows the results of the TPH analyses conducted at the laboratory.

In addition to the TPH analyses, the west wall sample was analyzed for total lead and resulted in a lead concentration of 30.8 mg/kg. A subsequent analysis for TCLP lead of the spoil pile materials resulted in a value of 7 μ g/L. Also, the spoil pile was analyzed for ignitability and was found to be non-ignitable.

None of the soils resulted in TPH concentrations greater than the 100 ppm TPH limit and therefore the soils were not remediated. The limit of TPH found in the soil is below the remedial criteria, and the TCLP lead levels are below regulatory limits. Thus, soils remain onsite to be used as general fill on the AANG property.

Laboratory analyses show that the soils remaining at the UST 380 site contain detectable levels of fuel component organic compounds. The compounds detected at the site are approximately 6 to 10 feet below the ground surface and do not present an exposure risk at ground surface unless excavated and exposed.

Table 2.1. Total Petroleum Hydrocarbons -UST 380 Pit		
Soil Sample Location	TPH Concentration (ppm)	
UST North Wall	9.6	
UST South Wall	2.7	
UST East Wall	<2.0	
UST West Wall	4.0	
UST Pit Bottom	5.2	
UST Spoil Pile	16.8	

On the basis of a well and spring inventory conducted during the site investigation, potential groundwater receptors are more than 1 mile from the UST 380 site.

3. CONTROL MEASURES

Control measures are addressed in this section of the Decision Document to consider the potential for adverse effects that could be caused by contaminants remaining at the UST 380 site.

3.1 SCREENING

Potential control measures used to manage the UST 380 site were screened to develop a technically feasible and reliable solution about the status of the former UST 380 site. The following criteria were used to identify and screen potential control measures for the former tank site.

- Known characteristics of the UST 380 site
- ADEM remedial criteria
- Technical feasibility of the control measure to safeguard human health and the environment

3.2 IDENTIFICATION

The following control measures were identified as possible alternatives using the screening criteria to meet the objectives of the IRP:

- Gather Additional SI Data
- Recommend remedial investigation (RI)
- No further action required (NFAR)

3.3 EVALUATION

The soils removed at UST 380 contained TPH levels showing that fuel components were a direct result of materials contained in UST 380 or by actions involved in the operations of UST 380. The soils that remain in the former UST 380's location indicate that a minor amount of petroleum-contaminated media exists (see Table 2.1).

Additional SI data could be used to determine if contamination of soils outside the immediate pit has occurred. However, the level of petroleum components that remains at the former UST site is less than ADEM's corrective action limits. It is suspected that further SI data would show only that contamination does not exist beyond the immediate soils adjacent to the pit.

A remedial investigation is not warranted because data that have been collected are below action levels set forth by ADEM.

4. CONCLUSIONS

Past operations at the UST 380 site led to this investigation because of possible soil and water contamination. Analytical results from soil samples obtained during this investigation indicate that the soil contains fuel component organic compounds. Soils within the excavation pit were found to have TPH concentrations lower than ADEM's criteria of 100 ppm. Discussions with ADEM field personnel indicated that additional excavation would not be required. ADEM documentation is included in the Appendix.

Appendix
ADEM Response to Closure Assessment Report

ALABAMA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT



Guy Hunt Gavernor

eigh Pegues, Director

May 8, 1991

1751 Cong. W. L. Dickinson Drive Montgomery, AL 36130 (205) 271-7700 FAX 271-7950 270-5612

Colonel Jim Copeland Alabama Air National Guard East Lake Boulevard Birmingham, Alabama 35217-3595

Field Offices:

Dear Colonel Copeland:

110 Vulcan Road Birmingham, AL 35209 (205)942-6168

FAX 941-1603

P.O. Box 953 Decatur, AL 35602 (205)353-1713 FAX 340-9359

2204 Perimeter Road Mobile, AL 36615 (205)479-2336

FAX 479-2593

RE: 117th Recon, East Lake Boulevard, Birmingham, Jefferson County, Alabama Facility Not Registered UST380, 211A and 211B

The Department has reviewed the underground storage tank closure assessment for the referenced site. As a result of this review it is determined that no further investigative or corrective actions will be required for this site at this time.

Please use a complete reference line in all future correspondence, including Facility Identification Number, name, address, and Incident Number (UST - -), where applicable. Sites that are not registered will not have an Identification Number and should be labeled (NOT REGISTERED). Because our filing system is dependent on the use of the Facility Identification Number, we may have to return correspondence and reports that do not provide this information.

If there are any questions, please contact me at 205/271-7835.

Sincerely,

イhadous W. Pittman Environmental Scientist Groundwater Branch Water Division

TWP/cmh

Because ADEM's corrective action limits were met and groundwater receptors are more than 1 mile away, it is recommended that the UST 380 site be removed from further IRP consideration and that no further action be required.

Signature:	Date:	
- 3	DAVID C. VAN GASBECK Chief, Environmental Division Air National Guard Readiness Center	
Signature:	Alchama Department of Environmental Management	<u></u>